

logo not found or type unknown

## DLCA Informs Public of Ford Bronco Sport and Escape SUV 2021-2022 Recall

Community Center / **Published On February 08, 2022 03:42 PM /**

Staff Consortium **February 08, 2022**

Image not found or type unknown



The V.I. Dept. of Licensing and Consumer Affairs on Tuesday informed the public of a recall announcement on certain 2021-2022 Bronco Sport and Escape SUV vehicles because of a potential reduction in the vehicles' power brake performance related to the rear brake lining.

According to Ford, the rear brake linings may have been manufactured incorrectly, which can affect braking performance. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 135, "Light Vehicle Brake Systems."

According to DLCA, during certain situations, the driver may have to apply more brake pedal force, and the distance required to stop the vehicle may be extended, increasing the risk of a crash. Ford said it is not aware of any accidents or injuries caused by this issue. A potential number of

115,000 vehicles are affected.

National Highway Traffic Safety Administration (NHTSA) has identified the cause as the friction coefficient of the rear brake-caliper linings being below specification. A NHTSA chronology explains that the agency conducted a stopping-distance test compliance audit on the 2021 Bronco Sport. It found that it took almost 192 meters (630 feet) to stop when the brake power assist unit was inoperative, compared with the federally regulated distance of 168 meters (551 feet).

Ford told NHTSA that its internal certification tests from December 2018 resulted in a stopping distance of just under 150 meters (492 feet). When Ford re-tested a vehicle under the same circumstances, it found that it took almost 178 meters (584 feet) to stop.”

DLCA said owner notification letters were expected to be mailed January 10, 2022. For more information on the vehicles that are subject to recall, contact Ford customer service at 1-866-436-7332. Ford’s number for this recall is 21C31.

DLCA encouraged all consumers to routinely check the NHTSA Website for any recalls that may affect the safe operations of their motor vehicle. This can be done at <https://www.nhtsa.gov/recalls>